

All Models

Rust Protection Procedure

User Instructions

Product:

1K ANTI-RUST PRODUCTS

NOVA POWER PAINT

+

NOVATIO:
SKIN COAT

2K ANTI-RUST PRODUCTS

A: PRIMER
B: ACTIVATOR

A: DUPONT® 2K ETCHING PRIMER
B: DUPONT® 2K ACTIVATOR 636R



A: STANDOX® ETCHING ADHESION
PRIMER 020 16167
B: STANDOX® ETCHING ADHESION
ACTIVATOR 020 16168

CAVITY WAX SPRAY

TEROSON WACHS
USB SPRAY
Ref: 794867



NOVATIO:
SKIN COAT

**Latest Version
SCAN HERE**



THINK BEFORE YOU PRINT



**ONLINE = LATEST VERSION
GO DIGITAL!**


Revision Record

Rev. No.	Date	Page	Step	Remarks
①	13.03.23	4, 5	8, 9	Time changed from 30 min. to 5 min.
②	05.10.23	3, 5, 6		Updated to latest standards
③	20.02.24	5		'Access both sides' Info removed Vacuum cleaner removed
③	20.02.24	6		'Access both sides' Info removed Vacuum cleaner removed

PREFERRED SUPPLIERS



TOOLS



CONSUMABLES

CLEANER

SAFETY CLEAN 01




DEGREASER

MULTI FOAM 02




CAVITY WAX SPRAY




**TEROSON WACHS
USB SPRAY
Ref: 794867**

or

**NOVATIO:
SKIN COAT**




1K ANTI RUST PRODUCTS




2K ANTI RUST PRODUCTS

A: Primer 020 16167
B: Activator 020 16168






2K ANTI RUST PRODUCTS

A: 1040R Universal 2K Primer Gray
B: 1010R HS Activator Fast



PERSONAL PROTECTION EQUIPMENT




USEFUL GENERAL MANUALS

CLEANER / DEGREASER



Latest Version
SCAN HERE



SYMBOLS



Latest Version
SCAN HERE



CONSUMABLES / CHEMICALS



Latest Version
SCAN HERE







Material Safety Data Sheet

Technical Data Sheet




CLEANER / DEGREASER



1

2

1K ANTI RUST







NOVA POWER PAINT 

3

4

CAVITY WAX



TEROSON® 


5

6



PREFERRED ANTI RUST PROTECTION!!!!
MANDATORY ON DRILLED CHROME

CLEANER / DEGREASER

SAFETY CLEAN 01



MULTI FOAM 02




X °C


1

2


2K ANTI RUST



2 mm



30 min.



21°C


3

4


5

CAVITY WAX


SKIN COAT




WX980



2 mm



5 min.



21°C

6



7